



# Aviation Investigation Final Report

<b>Location:</b>	Boston, Massachusetts	<b>Incident Number:</b>	DCA23LA192
<b>Date &amp; Time:</b>	February 27, 2023, 18:54 Local	<b>Registration:</b>	N280LJ (A1); N179JB (A2)
<b>Aircraft:</b>	LEARJET INC 60 (A1); Embraer ERJ 190-100 IGW (A2)	<b>Aircraft Damage:</b>	None (A1); None (A2)
<b>Defining Event:</b>	Air traffic event	<b>Injuries:</b>	N/A (A1); N/A (A2)
<b>Flight Conducted Under:</b>	Part 91: General aviation - Positioning (A1); Part 121: Air carrier - Scheduled (A2)		

## Analysis

JetBlue’s flight 206 (JBU206) flight crew initiated a go-around while over runway 04R due to Hop-a-Jet flight 280 (HPJ280) taking off without a takeoff clearance from runway 09 at Boston Logan International Airport (BOS).

Runways 04R and 09 at BOS are intersecting runways. The BOS tower controller had instructed the pilot of HPJ280 to line up and wait (LUAW) on runway 09 while JBU206 had been cleared to land on runway 04R. HPJ280’s flight crew read back the controller’s instructions to LUAW, however they began the takeoff-roll instead. The airport surface detection equipment, model X (ASDE-X) alerted, and the controller issued go-around instructions to JBU206.

JBU206’s flight crew initiated a go-around while over runway 04R, prior to reaching the intersection with runway 09. The closest proximity between both airplanes occurred when JBU206 was about 30ft AGL during the landing flare, close to the point where both runways intersected, see figure 1. A video file taken by the occupant of the flight deck observer seat was provided to the NTSB and a screen capture from the video is shown in figure 2.



Figure 1. Flight tracks of both JetBlue (JBU206) and Hop-a-Jet (HPJ280) with yellow circle indicating incursion area.



Figure 2: Screen capture from jump-seat occupant's video recording showing Lear 60 crossing runway centerline.

The captain of HPJ280 said that they had received clearance to cross runway 4L on taxiway E, and then take taxiway Mike, to Runway 9. On taxiway M he said, "they had heard a clearance that seems to be Line Up and Wait." He further stated that "he probably responded to the clearance, but in his mind, they were cleared for takeoff." He said they performed the takeoff at 18:55 local time, and during cruise they received a message from ATC providing them with a phone number to call upon landing. After landing at FXE, BOS tower told them that they had taken off without authorization and caused an airplane that had been cleared to land on runway 04 to execute a go-around, passing about 400' above them.

The first officer of JBU206 was the pilot flying, and they were on the ILS runway 04R approach. The captain of JBU206 said they had been cleared to land and had completed the landing checklist. On the tower frequency, they heard that an aircraft had been given LUAW instructions. As they entered the flare after crossing the threshold of runway 04R, about 30 feet above the ground, he saw an airplane cross 04R on runway 09 from his left and going to the right but could not estimate how far away the airplane was.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this incident to be:

The Hop-a-Jet flight crew taking off without a takeoff clearance which resulted in a conflict with a JetBlue flight that had been cleared to land on an intersecting runway.

### Findings

<b>Personnel issues (A1)</b>	Understanding/comprehension - Flight crew
<b>Environmental issues (A2)</b>	Aircraft - Effect on operation

## Factual Information

### History of Flight

<b>Takeoff (A1)</b>	Air traffic event (Defining event)
---------------------	------------------------------------

### Pilot Information (A1)

<b>Certificate:</b>	Airline transport	<b>Age:</b>	63, Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	4-point
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	
<b>Medical Certification:</b>	Class 1 With waivers/limitations	<b>Last FAA Medical Exam:</b>	February 14, 2023
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	January 11, 2023
<b>Flight Time:</b>	22544 hours (Total, all aircraft), 2317 hours (Total, this make and model), 16971 hours (Pilot In Command, all aircraft), 126 hours (Last 90 days, all aircraft), 51 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

### Co-pilot Information (A1)

<b>Certificate:</b>	Airline transport	<b>Age:</b>	23, Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	4-point
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	
<b>Medical Certification:</b>	Class 1 Without waivers/limitations	<b>Last FAA Medical Exam:</b>	October 25, 2022
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	June 30, 2022
<b>Flight Time:</b>	2027 hours (Total, all aircraft), 388 hours (Total, this make and model), 1649 hours (Pilot In Command, all aircraft), 160 hours (Last 90 days, all aircraft), 55 hours (Last 30 days, all aircraft)		

## Pilot Information (A2)

<b>Certificate:</b>	Airline transport	<b>Age:</b>	36, Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	5-point
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	Airplane multi-engine; Airplane single-engine	<b>Toxicology Performed:</b>	
<b>Medical Certification:</b>	Class 1 With waivers/limitations	<b>Last FAA Medical Exam:</b>	August 31, 2022
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	May 31, 2021
<b>Flight Time:</b>	7505 hours (Total, all aircraft), 1673 hours (Total, this make and model), 2817 hours (Pilot In Command, all aircraft), 71 hours (Last 90 days, all aircraft), 20 hours (Last 30 days, all aircraft)		

## Co-pilot Information (A2)

<b>Certificate:</b>	Airline transport	<b>Age:</b>	25, Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	5-point
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	Airplane multi-engine; Airplane single-engine; Instrument airplane	<b>Toxicology Performed:</b>	
<b>Medical Certification:</b>	Class 1 Without waivers/limitations	<b>Last FAA Medical Exam:</b>	November 30, 2022
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	December 28, 2022
<b>Flight Time:</b>	2280 hours (Total, all aircraft), 75 hours (Total, this make and model), 985 hours (Pilot In Command, all aircraft), 75 hours (Last 90 days, all aircraft), 47 hours (Last 30 days, all aircraft)		

### Aircraft and Owner/Operator Information (A1)

<b>Aircraft Make:</b>	LEARJET INC	<b>Registration:</b>	N280LJ
<b>Model/Series:</b>	60	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	2004	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Transport	<b>Serial Number:</b>	60-280
<b>Landing Gear Type:</b>	Retractable - Tricycle	<b>Seats:</b>	11
<b>Date/Type of Last Inspection:</b>		<b>Certified Max Gross Wt.:</b>	
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	2 Turbo fan
<b>Airframe Total Time:</b>		<b>Engine Manufacturer:</b>	P&W CANADA
<b>ELT:</b>		<b>Engine Model/Series:</b>	PW305A
<b>Registered Owner:</b>		<b>Rated Power:</b>	4679 Lbs thrust
<b>Operator:</b>		<b>Operating Certificate(s) Held:</b>	On-demand air taxi (135)

### Aircraft and Owner/Operator Information (A2)

<b>Aircraft Make:</b>	Embraer	<b>Registration:</b>	N179JB
<b>Model/Series:</b>	ERJ 190-100 IGW	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	2005	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Transport	<b>Serial Number:</b>	19000006
<b>Landing Gear Type:</b>	Retractable - Tricycle	<b>Seats:</b>	20
<b>Date/Type of Last Inspection:</b>		<b>Certified Max Gross Wt.:</b>	
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	2
<b>Airframe Total Time:</b>		<b>Engine Manufacturer:</b>	AMA/EXPR
<b>ELT:</b>		<b>Engine Model/Series:</b>	UNKNOWN ENG
<b>Registered Owner:</b>		<b>Rated Power:</b>	
<b>Operator:</b>		<b>Operating Certificate(s) Held:</b>	Flag carrier (121)



## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Night
<b>Observation Facility, Elevation:</b>	BOS,19 ft msl	<b>Distance from Accident Site:</b>	0 Nautical Miles
<b>Observation Time:</b>	15:54 Local	<b>Direction from Accident Site:</b>	0°
<b>Lowest Cloud Condition:</b>	Few / 4600 ft AGL	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	Overcast / 6000 ft AGL	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	6 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	330°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29.83 inches Hg	<b>Temperature/Dew Point:</b>	2°C / -7°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Boston, MA (A1); Nashville, TN (KBNA) (A2)	<b>Type of Flight Plan Filed:</b>	IFR (A1); IFR (A2)
<b>Destination:</b>	Fort Lauderdale, FL (KFXE) (A1); Boston, MA (A2)	<b>Type of Clearance:</b>	None (A1); IFR (A2)
<b>Departure Time:</b>	16:05 Local (A2)	<b>Type of Airspace:</b>	

## Airport Information

<b>Airport:</b>	Boston-Logan International Airport KBOS	<b>Runway Surface Type:</b>	Asphalt
<b>Airport Elevation:</b>	19 ft msl	<b>Runway Surface Condition:</b>	
<b>Runway Used:</b>	04L	<b>IFR Approach:</b>	Unknown
<b>Runway Length/Width:</b>	7864 ft / 150 ft	<b>VFR Approach/Landing:</b>	

## Wreckage and Impact Information (A1)

<b>Crew Injuries:</b>	N/A	<b>Aircraft Damage:</b>	None
<b>Passenger Injuries:</b>	N/A	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>		<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	N/A	<b>Latitude, Longitude:</b>	42.366978,-71.022362

## Wreckage and Impact Information (A2)

<b>Crew Injuries:</b>	N/A	<b>Aircraft Damage:</b>	None
<b>Passenger Injuries:</b>	N/A	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>		<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	N/A	<b>Latitude, Longitude:</b>	42.366978,-71.022362

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Lovell, John		
<b>Additional Participating Persons:</b>	Marco Devarez; JetBlue Doug Spanier; Hop A Jet		
<b>Original Publish Date:</b>	August 3, 2023	<b>Investigation Class:</b>	4
<b>Note:</b>	The NTSB did not travel to the scene of this incident.		
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=106806">https://data.nts.gov/Docket?ProjectID=106806</a>		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).